


NOTE: If Totaling (Accumulation), pressing the "ON/ PRINT" button will print the load's weight information and then add the weight to the total weight. To print total weight, hold the "ON/PRINT" Button for three seconds, then, while indicator flashes press the "ON/PRINT" Button again.


The display indicator can be toggled between lbs and kg. Refer to Display Indicator Functions section. Printer output is in units selected during calibration.



## **OPERATOR'S POCKET GUIDE**

## **C-Series**Weigh Forks

## **DISPLAY INDICATOR FUNCTIONS**



FK1080.ai

**NOTE:** For more information on display functions, refer to the C-Series Weigh Forks User Manual 8305557.

	Short Button Press	Long Button Press
UNITS	Toggle Units	N/A
ZERO OFF	Zero	Turn Indicator Off
SET NET GROSS	Toggle between Gross & Net weight	N/A
TARE	Establish or Cancel Tare Weight	N/A
ON PRINT	Print Weight	Turn Indicator On

Manual Number 8305558-R2




Cascade is a Registered Trademark of Cascade Corporation





## **IMPORTANT**:

- At initial daily start up, allow 3-5 minutes for the forks to warm up before weighing loads.
- The system will not weigh correctly if the front face or bottom of the forks touches the load and pallet.
- Unstable weight readings indicate debris between fork and fork shoe.




Press the "ON/PRINT" button. Wait 5 seconds.





- When weighing liquids, more time is needed for indicator to show a steady weight.
- Do not exceed fork length by more than 6 in. (152 mm) with load length.



Display will zero. If necessary, zero manually.

Verify forks are free of obstacles prior to zeroing.



The display indicator can be toggled between lbs and kg. Refer to Display Indicator Functions section in the user manual (part no. 8314244). Printer output is in units selected during calibration.

Weigh load. Before next weighing, check zero point.



FK1086.ai